

	Troubleshooting Guide: Drive Belt Slipping		
Prepared by: Lee Trask	Date Prepared: 12/30/2016	Effective Date: 11/14/2011	Models Affected: R10 (RB153)

PROBLEM

Directly out of the box, the drive belt slips while pedaling.

REQUIRED TOOLS

6 mm wrench

SOLUTION

1. Check the tension idler—it should bounce with the spring stretching at each stride.
2. If the idler does not move, the nut holding the idler assembly might be too tight. Loose this nut with a 6 mm wrench. The correct nut is shown in images below.



