

How To Access Eng. Mode & — Horizon CT 5.1

- 1) Press and hold stop button until it beeps 2 times in a row.
- 2) Remove safety key and then replace.
- 3) Press the incline ^ and speed down – until you see EN90.
- 4) Use the incline arrow buttons to navigate the screen. (EN 91 test console and elevation, EN92 for auto calibration for controller and drive motor.)
- 5) Press Enter, then start. Unit should calibrate it self.