



Silver Trading Enterprise Co., Ltd.

Exclusive International Marketing and Sales
of Greenmaster Industrial Corp.

PRODUCT PROCESS SHEET


Model No.: CE7.4 / REV600 / X1 / X2

PPS-SMOOTH-Magnetic system-20090302


Page 1 of 1

A: AGILE, CE7.4, REV600

B: X1, X2




1. Adjust the multimeter to the OHM, Use the red test lead and black test lead to touch the female.



1. If the multimeter display is shown about 160, the magnetic system is good. If the the multimeter display is shown 0, the magnetic system is bad.



1. Adjust the multimeter to the OHM, Use the red test lead and black test lead to touch the female.



1. If the multimeter display is shown about 200, the magnetic system is good. If the the multimeter display is shown 0, the magnetic system is bad.

