



SERVICE

XT9 Calibration

1. Remove tether cord. Press and hold the START and FAST buttons and put tether cord back on. Display will go into test mode. Press ENTER.
2. "UNITS" English or Metric will scroll along the bottom of the display. Use UP or DOWN buttons to change. Press ENTER.
3. "ADJUST WHEEL SIZE" will scroll along the bottom of the display and a number will flash in the calorie window. Use UP or DOWN buttons to change. (2.43) Press ENTER.
4. "ADJUSTS MIN SPEED" will scroll along the bottom of the display and a number will flash in the calorie window. Use UP or DOWN buttons to change. (0.5) Press ENTER.
5. "ADJUST MAX SPEED" will scroll along the bottom of the display and a number will flash in the calorie window. Use UP or DOWN buttons to change. (10.0) Press ENTER.
6. "ADJUST MAX ELEVATION" will scroll along the bottom of the display and a number will be in the calorie window. Use UP or DOWN buttons to change. (14) Press ENTER.
7. "GRADE RETURN" will scroll along the bottom of the display and "ON" or "OFF" will be in the calorie window. Use UP or DOWN to change. (ON)

WARNING - DO NOT STAND ON BELT FOR NEXT STEP

8. Press START. Unit will now auto-calibrate speed then incline. Unit will reset when it completes calibration.