

STAR TRAC 1800 SERIES ENGINEERING MODE

1. Press and hold simultaneously: 'scan track', 'Track Profile' & 'Incline Dn'
2. Release 'Track Profile' only. You should see Engineering Mode on Screen
3. Press 'Cool Down' then 'Enter'
4. Use Incline up to scroll to options

