

	Troubleshooting Guide: Mast is Not Centered
Date Prepared: 9/29/2015	Models Affected: All Recumbent and Upright Bikes

PROBLEM

The mast is not centered.

SOLUTION

1. Check for missing hardware.
2. Loosen all of the mast bolts. If the mast leans left, press and hold the mast toward the right while retightening the bolts, and vice versa.
3. If the issue remains, ask the customer to visually inspect and send photos of the weld where the mast connects to the frame.