


Body-Solid




BODY-SOLID, Inc.
1900 S. Des Plaines Ave.
Forest Park, IL 60130 USA
Phone: (708) 427-3555
Fax: (708) 427-3556
www.bodysolid.com

EXM-3550 OWNER'S MANUAL

EXM-3550 ASSEMBLY INSTRUCTIONS

HARDWARE ILLUSTRATION

A1		A1. 1/2"X4 1/4" HEX HEAD BOLT-----	[10PCS]
A2		A2. 1/2"X3" HEX HEAD BOLT-----	[8PCS]
A3		A3. 1/2"X2 3/4" HEX HEAD BOLT-----	[2PCS]
A4		A4. 3/8"X4 1/4"HEX HEAD BOLT-----	[2PCS]
A5		A5. 3/8"X4" HEX HEAD BOLT-----	[4PCS]
A6		A6. 3/8"X3 3/4" HEX HEAD BOLT-----	[1PCS]
A7		A7. 3/8"X1 3/4" HEX HEAD BOLT-----	[9PCS]
A8		A8. 5/16"X2" HEX HEAD BOLT-----	[2PCS]
A9		A9. 5/16"X1" HEX HEAD BOLT-----	[14PCS]
A10		A10. 3/8"X2" ROUND BOLT -----	[1PCS]
A11		A11. 5/16"X3/4" ROUND BOLT-----	[8PCS]
A12		A12. M10x80L ROUND BOLT-----	[2PCS]
A13		A13. M10x65L ROUND BOLT-----	[4PCS]
A14		A14. M10x40L ROUND BOLT-----	[2PCS]
A15		A15. 10LB PIN(8250-047)-----	[1PCS]
A16		A16. STEEL CHAIN -----	[1PCS]
A17		A17. 1/2"X3 1/2" HEX HEAD BOLT-----	[2PCS]
A18		A18. 5/16"X1 3/4" HEX HEAD BOLT-----	[1PCS]
A19		A19. 3/8"X3" HEX HEAD BOLT-----	[2PCS]
B1		B1. 1/2" Nylon Lock Nut-----	[19PCS]
B2		B2. 3/8" Nylon Lock Nut-----	[13PCS]
B3		B3. M10 Nylon Lock Nut-----	[8PCS]
B4		B4. 5/16" Nylon Lock Nut-----	[1PCS]
C1		C1. 1/2"XØ34 (I.D)WASHER-----	[33PCS]
C2		C2. 1/2"XØ25 (I.D)WASHER-----	[8PCS]
C3		C3. 3/8" WASHER-----	[31PCS]
C4		C4. 5/16" WASHER-----	[26PCS]
C5		C5. M10 WASHER-----	[8PCS]
C6		C6. 5/16" SPRING WASHER-----	[24PCS]



HARDWARE ILLUSTRATION

D26. Ø110X50 PULLEY (9213-022A)-----	[1PCS]
D27. Ø110X50 PULLEY (9213-022C)-----	[3PCS]
D28. 2"X2" RUBBER CANE CAP (9214-002)-----	[2PCS]
D29. Ø51XØ38 FASTENING HOLDER (9219-003)-----	[1PCS]
D30. Ø51XØ38 FASTENING HOLDER (9219-004)-----	[1PCS]
D31. Ø1" ROUND END CAP (9260-021)-----	[4PCS]
D32. Ø55 RUBBER DOUNT (9310-027)-----	[2PCS]
D33. 95X140mm NO-SLIP TAPE (9310-035) -----	[4PCS]
D34. 6180mm STEEL CABLE-----	[1PCS]
D35. 5780mm STEEL CABLE-----	[1PCS]
D36. 1800mm STEEL CABLE-----	[1PCS]
D37. 1135mm STEEL CABLE-----	[1PCS]
D38. 600mm STEEL CABLE-----	[1PCS]

D26




D32



D27



D33




D34




D28



D35



D29



D36



D30



D37



D31



D38




D39




PARTS ILLUSTRATION SHEET


A [1PCS]




B [1PCS]




C [1PCS]




D [1PCS]



E [1PCS]




F [1PCS]




PARTS ILLUSTRATION SHEET


H [1PCS]




G [1PCS]




I [1PCS]



J [1PCS]




M [1PCS]




K [2PCS]



L [1PCS]




P [1PCS]




N [2PCS]



O [1PCS]




Q [1PCS]




PARTS ILLUSTRATION SHEET


R [1PCS]




S [2PCS]




T [1PCS]



U [1PCS]



V [1PCS]




W [2PCS]




Y [2PCS]




Z [1PCS]




AA [1PCS]




X [1PCS]



AB [1PCS]




AC [2PCS]



AD [1PCS]




AE [4PCS]



AF [1PCS]




AG [1PCS]



AH [1PCS]




AI [1PCS]




PARTS ILLUSTRATION SHEET


AI [1PCS]




AJ [1PCS]




AK [1PCS]




AL [1PCS]



AM [1PCS]




AN[1PCS]




AP[4PCS]




AQ[1PCS]




AR[1PCS]




AS[1PCS]




AT[1PCS]




ASSEMBLY STEP 1




ASSEMBLY STEP 2




ASSEMBLY STEP 3



ASSEMBLY STEP 4





ASSEMBLY STEP 5




Wire Rope illustration 1

D37






Wire Rope illustration 2




Wire Rope illustration 3

D38




Wire Rope illustration 4

D36




W VIEW



Wire Rope illustration 5

D39



ASSEMBLY STEP 6

