

Troubleshooting Guides – Energy Saver Mode



Date Prepared: 9/3/2013	Models Affected: Treadmill Classic console (TM435)
----------------------------	---

If Energy Saver Mode (ESM) does not function correctly on the console (ex. the console wakes up without user input), update the console software to the current version.