

Owner's Guide – Warranty



Date Prepared: 10/23/2014	Models Affected: ST200 (GM89, GM77)
------------------------------	--

A marketing brochure was released that listed different warranty coverage than the terms in the owner's guide.

If a customer has a copy of the marketing materials, JHTNA will honor those warranty terms. The customer must provide a copy of the marketing sheet with the incorrect warranty information.

Revision Date: 5/25/2018 | Revised by: EM